Timesheet

Job #: _____

STOCK LOCATIONS: mastw13e

WELDMENT: A01841 - MOUNT PLATE

Serial: _____

Quantity: _____

Page 1 of 1

| STEP | Machine # | Route ID | BADGE # | Cycle or Setup Time (minutes) | Qty Passed | Qty Rejected | Std Time 1 pc. (Minutes) |
|---------|--------------|----------|---------|----------------------------------|---------------|-----------------|-----------------------------|
| Setup 1 | VF3-carriage | M6081 | | | | | 5 |
| Cycle 1 | | | | | | | 10 |

Problems (circle all that apply)

Missing Parts Lack of Tools Poor Material Rework

work Network Issues