Timesheet

Job #: _____

STOCK LOCATIONS: 89B

Problems (circle all that apply)

shaftw1b

WELDMENT: A17281-2 - ROLLER SHAFT

Serial: _____

Quantity: _____

Network Issues

Page 1 of 1

STEP	Machine #	Route ID	BADGE #	Cycle or Setup Time (minutes)	Qty Passed	Qty Rejected	Std Time 1 pc. (Minutes)
Setup 1	VF2-chassis	M5141					0
Cycle 1							5
Problems (circle all that apply)		Missing Parts Lack of Tools		ols Poor Material	Rework	Network Issues	
STEP	Machine #	Route ID	BADGE#	Cycle or Setup Time (minutes)	Qty Passed	Qty Rejected	Std Time 1 pc. (Minutes)
Setup 1	SL30	M6142					0
Cycle 1							40

Missing Parts Lack of Tools Poor Material Rework