

Timesheet

Job #: _____

STOCK LOCATIONS: STEERAXLE5B

WELDMENT:A18604 - STEER AXLE FRAME LOWER PLATE

Serial: _____

Quantity: _____

Page 1 of 1

STEP	Machine #	Route ID	BADGE #	Cycle or Setup Time (minutes)	Qty Passed	Qty Rejected	Std Time 1 pc. (Minutes)
Setup 1	VF11	M5202					0
Cycle 1							70

Problems (circle all that apply)

Missing Parts Lack of Tools Poor Material Rework Network Issues