_	-		_
	ime	eh	ΔΔt
		JII	ししし

Job #: _____

STOCK LOCATIONS:

WELDMENT: A23975 - SIDE PLATE - PUSHER

Serial: _____

Quantity: _____

Page 1 of 1

STEP	Machine #	Route ID	BADGE #	Cycle or Setup Time (minutes)	Qty Passed	Qty Rejected	Std Time 1 pc. (Minutes)
Setup 1	VF7	M4085					30
Cycle 1							30

Problems (circle all that apply)

Missing Parts Lack of Tools Poor Material Rework

Network Issues