_		
- 1	imesheet	
	11116311661	

Job #:	

STOCK LOCATIONS:

WELDMENT: B21591-1 - MAIN STAGE TUBE WELDMENT

Serial:	
---------	--

Quantity: _____

Page 1 of 1

STEP	Machine #	Route ID	BADGE#	Cycle or Setup Time (minutes)	Qty Passed	Qty Rejected	Std Time 1 pc. (Minutes)
Setup 1	TL4	M4081					30
Cycle 1							90

Problems (circle all that apply)

Missing Parts Lack of Tools Poor Material Rework

Network Issues